 7

Textile Testing

553 76th Street · Byron Center, MI 49315 Phone: 616.559.6123 Fax: 616.559.6119

Report Number: 34801

Date: 05-12-09

For the Account Of:

Pollack

150 Varick St

New York, NY 10013

Contact:

Larry Hoysic

Client's Identification:

Dapper

Test Performed

California Technical Bulletin 117, Section E (CPSC 16 CFR 1610 - CS 191-53) Upholstery

Fabrics

TEST DATA

☐ Raised Surface

	Flame Spread	Flame Spread
	Warp Face	Warp Back
Specimen	(seconds)	(seconds)
1	DNI	
2	DNI	
3	DNI	
4		DNI
5		DNI
	Flame Spread	Flame Spread

Specimen	Flame Spread Fill Face (seconds)	Flame Spread Fill Back (seconds)	_
1	DNI		_
2	DNI		
3	DNI		
4		DNI	
5		DNI	

ABBREVIATIONS USED

Did not ignite when exposed to test ignition source DNI

IBE Ignited but extinguished before burning through stop cord

SF Surface flash only; stop cord not burned & no burning/charring/fusing of the base fabric **TSF**

Timed surface flash; stop cord burned, but no burning/charring/fusing of the base fabric

ACCEPTANCE CRITERIA

- 1. With nap Minimum flame spread of any individual specimens shall be 7 seconds.
- 2. Without nap Minimum flame spread of any individual specimens shall be 3.5 seconds.

CONCLUSION

Based on the above Results and Acceptance Criteria, the item tested:

☐ Does Not Comply

CERTIFICATION: I certify that the above results were obtained after testing specimen in accordance with the procedures and equipment specified by the standard stated above.