Textile Testing

553 76th Street · Byron Center, MI 49315 Phone: 616.559.6123 Fax: 616.559.6119

Report Number: 29575

Date: 8/5/2008

For the Account Of:

Pollack

150 Varick Street

10th Floor

New York, NY 10013-1218

Contact:

Larry Hoysic

Client's Identification:

Fleury

Test Performed

California Technical Bulletin 117, Section E (CPSC 16 CFR 1610 - CS 191-53) Upholstery

Fabrics

TEST DATA

Raised Surface

Specimen	Flame Spread Warp Face (seconds)	Flame Spread Warp Back (seconds)	
1	DNI		
2	DNI		
3	DNI		
4		DNI	
5		DNI	

	Flame Spread Fill Face	<u>Flame Spread</u> Fill Back	
Specimen	(seconds)	(seconds)	
1	DNI		
2	DNI		
3	DNI		
4		DNI	
5		DNI	

ABBREVIATIONS USED

DNI Did not ignite when exposed to test ignition source

IBE Ignited but extinguished before burning through stop cord

SF Surface flash only; stop cord not burned & no burning/charring/fusing of the base fabric **TSF** Timed surface flash; stop cord burned, but no burning/charring/fusing of the base fabric

ACCEPTANCE CRITERIA

- 1. With nap Minimum flame spread of any individual specimens shall be 7 seconds.
- 2. Without nap Minimum flame spread of any individual specimens shall be 3.5 seconds.

CONCLUSION

Based on the above Results and Acceptance Criteria, the item tested:

□ Complies

□ Does Not Comply

CERTIFICATION: I certify that the above results were obtained after testing specimen in accordance with the procedures and equipment specified by the standard stated above.

Page 1 of 1

