Textile Testing

553 76th Street Byron Center, MI 49315 Phone: 616.559.6123 Fax: 616.559.6119

Report Number: 34371 Date: 04-21-09

For the

Pollack

Account Of: 150 Varick St

New York, NY 10013

Contact:

Larry Hoysic

Client's

Florasian

Identification:

Test Performed California Technical Bulletin 117, Section E (CPSC 16 CFR 1610 - CS 191-53) Upholstery

Fabrics

TEST DATA

☐ Raised Surface

Specimen	Flame Spread Warp Face (seconds)	Flame Spread Warp Back (seconds)
1	DNI	
2	DNI	
3	DNI	
4		DNI
5		DNI

		
	Flame Spread Fill Face	<u>Flame Spread</u> <u>Fill Back</u>
Specimen	(seconds)	(seconds)
1	DNI	
2	DNI	
3	DNI	
4		DNI
5		DNI

ABBREVIATIONS USED

Did not ignite when exposed to test ignition source DNI

IBE Ignited but extinguished before burning through stop cord

Surface flash only; stop cord not burned & no burning/charring/fusing of the base fabric SF **TSF**

Timed surface flash; stop cord burned, but no burning/charring/fusing of the base fabric

ACCEPTANCE CRITERIA

- 1. With nap Minimum flame spread of any individual specimens shall be 7 seconds.
- 2. Without nap Minimum flame spread of any individual specimens shall be 3.5 seconds.

CONCLUSION

Based on the above Results and Acceptance Criteria, the item tested:

☐ Does Not Comply

CERTIFICATION: I certify that the above results were obtained after testing specimen in accordance with the procedures and equipment specified by the standard stated above.