## Textile Testing

553 76<sup>th</sup> Street · Byron Center, MI 49315 Phone: 616.559.6123 Fax: 616.559.6119

Report Number: 30754

Date: 9/29/2008

For the Account Of:

Pollack

150 Varick Street New York, NY 10013

Contact:

Larry Hoysic

Client's Identification:

Starlight Velvet

**Test Performed** 

California Technical Bulletin 117, Section E (CPSC 16 CFR 1610 - CS 191-53) Upholstery

**Fabrics** 

**TEST DATA** 

☐ Raised Surface

	Flame Spread Warp Face	<u>Flame Spread</u> <b>Warp Back</b>	
Specimen	(seconds)	(seconds)	
1	DNI		
2	DNI		
3	DNI		
4		DNI	
5		DNI	

Specimen	Flame Spread Fill Face (seconds)	Flame Spread Fill Back (seconds)
1	DNI	
2	DNI	
3	DNI	
4		DNI
5		DNI

## **ABBREVIATIONS USED**

Did not ignite when exposed to test ignition source DNI

**IBE** Ignited but extinguished before burning through stop cord

Surface flash only; stop cord not burned & no burning/charring/fusing of the base fabric SF **TSF** 

Timed surface flash; stop cord burned, but no burning/charring/fusing of the base fabric

## **ACCEPTANCE CRITERIA**

- 1. With nap Minimum flame spread of any individual specimens shall be 7 seconds.
- 2. Without nap Minimum flame spread of any individual specimens shall be 3.5 seconds.

CONCLUSION

Based on the above Results and Acceptance Criteria, the item tested:

☐ Does Not Comply

CERTIFICATION: I certify that the above results were obtained after testing specimen in accordance with the procedures and equipment specified by the standard stated above.