Textile Testing 553 76th Street · By

553 76th Street · Byron Center, MI 49315 Phone: 616.559.6123 Fax: 616.559.6119

Report Number: 37754 Date: 11-17-09

For the Account Of:

Pollack

150 Varick St

New York, NY 10013

Contact:

Larry Hoysic

Client's Identification:

Quilted Paisley

Test Performed

California Technical Bulletin 117, Section E (CPSC 16 CFR 1610 - CS 191-53) Upholstery

Fabrics

TEST DATA

Raised Surface

Specimen	Flame Spread Warp Face (seconds)	Flame Spread Warp Back (seconds)	
1	DNI		
2	DNI		
3	DNI		
4		DNI	
5		DNI	

Flame Spread Fill Face (seconds)	Flame Spread Fill Back (seconds)
DNI	
DNI	
DNI	
	DNI er genjege stoja
	DNI
	Fill Face (seconds) DNI DNI

ABBREVIATIONS USED

DNI Did not ignite when exposed to test ignition source

IBE Ignited but extinguished before burning through stop cord

SF Surface flash only; stop cord not burned & no burning/charring/fusing of the base fabric

TSF Timed surface flash; stop cord burned, but no burning/charring/fusing of the base fabric

ACCEPTANCE CRITERIA

- 1. With nap Minimum flame spread of any individual specimens shall be 7 seconds.
- 2. Without nap Minimum flame spread of any individual specimens shall be 3.5 seconds.

CONCLUSION

Based on the above Results and Acceptance Criteria, the item tested:

□ Complies

☐ Does Not Comply

CERTIFICATION: I certify that the above results were obtained after testing specimen in accordance with the procedures and equipment specified by the standard stated above.

Authorized Signature

