Tex 553

Textile Testing 553 76th Street · Byron Center, MI 49315 Phone: 616,559,6123 Fax: 616,559,6119

Report Number: 26464 Date: 02/28/2008

For the Account Of:

Pollack

150 Varick St

New York, NY 10013

Contact:

Larry Hoysic

Client's Identification:

Quarry Stones

Test Performed

California Technical Bulletin 117, Section E (CPSC 16 CFR 1610 - CS 191-53) Upholstery

Fahrice

TEST DATA

☐ Raised Surface

Specimen	Flame Spread Warp Face (seconds)	Flame Spread <u>Warp Back</u> (seconds)	
1	DNI		
2	DNI		
3	DNI		
4		DNI	
5		DNI	

Specimen	Flame Spread Fill Face (seconds)	Flame Spread Fill (seconds)
1 2	DNI DNI	
3 4 5	DNI	DNI DNI

ABBREVIATIONS USED

DNI Did not ignite when exposed to test ignition source

IBE Ignited but extinguished before burning through stop cord

SF Surface flash only; stop cord not burned & no burning/charring/fusing of the base fabric

TSF Timed surface flash; stop cord burned, but no burning/charring/fusing of the base fabric

ACCEPTANCE CRITERIA

- 1. With nap Minimum flame spread of any individual specimens shall be 7 seconds.
- 2. Without nap Minimum flame spread of any individual specimens shall be 3.5 seconds.

CONCLUSION Based on the above Results and Acceptance Criteria, the item tested:

☐ Does Not Comply

CERTIFICATION: I certify that the above results were obtained after testing specimen in accordance with the procedures and equipment specified by the standard stated above.

Authorized Signature