

## CERTIFICATE OF TESTING

For The Account Of:

Pollack

150 Varick St

New York, NY 10013

DATE: August 27, 2007

CERTIFICATE (ORDER) NO.: 23354

**CLIENT'S IDENTIFICATION:** 

Structure 4119

## CAL117, Section E, Part I - Upholstery Fabrics (CS 191-53) Plain Surface

Specimen	Flame Spread Warp (seconds)	Without Nap (Plain Surface) FACE	Specimen	Flame Spread Warp (seconds)	Without Nap (Plain Surface) BACK
1	DNI	X	1		
2	DNI	X	2		
3	DNI	X	3		
4			4	DNI	X
5			5	DNI	X

Specimen	Flame Spread Fill (seconds)	Without Nap (Plain Surface) FACE	Specimen	Flame Spread Fill (seconds)	Without Nap (Plain Surface) BACK
1	DNI	X	1		
2	DNI	X	2		
3	DNI	X	3		
4			4	DNI	X
5			5	DNI	X

- DNI Did not ignite when exposed to test ignition source
- IBE Ignited but extinguished before burning through stop cord.
- SF Surface flash only; stop cord not burned & no burning/charring/fusing of the base fabric.
- TSF Timed surface flash; stop cord burned, but no burning/charring/fusing of the base fabric.

Requirements: With nap - Minimum flame spread of any individual specimens shall be 7 seconds.

Requirements: Without nap - Minimum flame spread of any individual specimens shall be 3.5 seconds.

Conclusion: The above results indicate **COMPLIANCE** with the stated requirements.

I certify that the above results were obtained after testing specimens in accordance with the procedures and equipment specified by California Technical Bulletin 117, Section E, Part I Upholstered Fabrics dated January 1980.

Lab Manager: Sallie Cotey

Lab Technician: Chavon McDaniel

Charan Mc Daniel